# OE Replacement for OE Performance

If replacement injectors are needed, use only genuine Bosch new or remanufactured injectors or injectors from an Authorized Bosch Common Rail Field Repair location.

- Remanufactured/Repaired using genuine OE parts
- Meets OEM performance and emission requirements

0 986 435 XXX

non Bail Ini

Bosch Authorized part label





To find a local Bosch Diesel Service Center, visit:

www.boschservice.com

Robert Bosch LLC Broadview, Illinois 60155


Robert Bosch, Inc. Mississauga, Ontario L5N 1R1

www.boschautoparts.com www.bosch.ca

17102435

@2017 Robert Bosch LLC, USA. All rights reserved. BOSCH is a registered trademark of Robert Bosch GmbH and/or its affiliated entities.

For more information visit: www.boschautoparts.com



# Bosch Common Rail Injectors

Potential Failures and Causes



Bosch Authorized test equipment

# You're telling me I need new injectors, what happened?

The diesel fuel system supplies, transfers, cleans and delivers fuel to the engine cylinders to facilitate combustion, thereby producing power.

# Filtration



# **Fuel Contamination and Corrosion**





New Bosch Valve Body

uniform grinding on A orifice

## Incorrect Installation



#### Causes:

- Missing sealing ring
- ► Incorrect procedure and/or tightening torque when installed

### Effect:

▶ Black smoke ► Poor performance

# The key causes of injector failures are:

- Poor Fuel Filtration
- Fuel Contamination
- Incorrect Installation

#### **Poor Fuel Filtration**

A common problem with diesel injectors today is ball seat erosion. The heart of the common rail injector is the magnetic valve through which fuel passes at extremely high pressure. The

#### Causes:

Causes:

- ► Inadequate filtration
- ► Poor quality fuel supply
- ► Inadequate maintenance intervals
- Effect: ► Starting problems
- ► Poor performance
- ► Idling problems
- (vibration)

► Water in fuel

Poor quality fuel supply ► Inadequate filtration.

### Effect:

- ► Poor performance
- (vibration)
- water separation
- interval

► Idling problems

Cause:

Effect:

► Misfire

(MIL)

torque

► Incorrect tightening

► Check Engine Light

- ► Inadequate maintenance

# **Stretched Solenoid Studs**



passage opening is sealed using a small ball that is only 1mm in size. A proper seal is critical for proper injector performance. Abrasive contaminants can erode and damage the ball seat causing the ball not to seal properly, leading to improper injection.

To ensure exact performance within the designed service life of the injector, use only OE filters or filters having the same OE micron rating and follow the recommended OE filter change interval. Using anything less can cost you more in the long run.

### **Fuel Contamination**

Repair statistics show that the majority of diesel engine problems stem from contaminated fuel. One of the most common problems with diesel injectors is corrosion. which is caused by water in the fuel.

How does the water get into the fuel? A vented cap allows air to enter the storage tank to equalize pressure as the fuel flows out. The outside air contains moisture and this moisture condenses into water inside the tank.

Always purchase fuel from a reputable service provider and use a proper fuel/ water separator.

### Incorrect Installation

Missing sealing rings, incorrect tightening torque and incorrect cleaning of nozzle can cause poor performance, misfiring, black smoke and check engine light (MIL) to appear.

Always follow the engine manufacturer's maintenance procedures.

